

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, September 26, 2018	Project Contact:	Brian Clauto
Spread: Franklin County	Spread I	Weather (Wet/Dry/Rain):	Wet

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing
 ☐ Rough Grading
 ☒ Trench Excavation
 ☒ Pipe Assembly, Testing & Installation
☒ Backfilling and Grade Restoration
 ☐ Final Grading & Stabilization
 ☐ Other:

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |


Comments / Observations:

- **Area 1** – MP 265 St#14000+09 crews on site removing sediment off ROW
- **Area 2** - MP 265 St#14000+09 ECD requires maintenance

Adjacent property not associated with pipeline near St#14000+09 has discharged onto ROW and may have affected the ECD at ST#14000+09.

Deadline: Within 24hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:  Date: 11-5-18

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, September 26, 2018

Fig. 1

Adjacent property not associated with pipeline near St#14000+09 discharging onto ROW.



Fig. 2

Area off of ROW near St#14000+09 impacted by sediment.



Fig. 3

St#140009+00 ECD requires maintenance



Fig. 4

St# 13998+00 sediment has been removed.

